

FORD LDM Localization - 功能 #2548

功能 # 2519 (已关闭): Ford_SYSR: System Requirement

Ford_SYSR : FS_REQ0028_V1 DRL Response to Low Beam outage

2024-10-24 18:06 - 玉洁 金

状态:	已关闭	开始日期:	2024-10-29
优先级:	普通	计划完成日期:	2024-11-07
指派给:	云浩 汪	% 完成:	100%
类别:		预期时间:	0.00 小时
目标版本:	H004_SW0007169.A002.0	耗时:	0.00 小时
描述			
DRL maybe affected by LB if LB outage is detected and configured to be turned off, a configurable parameter “ DRL_LB_Outage_cfg ” will determine if DRL is affected by LB outage. 0x00h: DRL will not be affected by LB outage. 0x01h: DRL will be affected by LB outage. When LB failure and LB is configured to turn off with failure, If DRL requested, DRL will dim to “ ParkPos_Intensity_cfg ” ; If POS requested, it should keep “ ParkPos_Intensity_cfg ” . 0x02h: DRL will be affected by LB outage. When LB failure and LB is configured to turn off with failure, If DRL requested, it can be activated with ‘ DRL_Intensity_cfg ’ ; If POS requested, it should be off.			
子任务:			
功能 # 2878: Ford_SWER_0028_0001 : DRL Response to Low Beam outage...			已关闭
功能 # 3001: Ford_SWER_0028_0002 : DRL Response to Low Beam outage...			已关闭

历史记录

#1 - 2024-10-25 09:46 - 涛 陆

完成

#2 - 2024-10-31 16:05 - 斌 徐

- 状态 从 新建 变更为 进行中

#3 - 2024-11-05 09:09 - 涛 陆

- 状态 从 进行中 变更为 反馈

- 目标版本 从 H003_SW0007169.A001.8 变更为 H004_SW0007169.A002.0

目前项目无此需求，待需求确认再开发

#4 - 2024-11-27 09:58 - 斌 徐

- 状态 从 反馈 变更为 已解决

#5 - 2024-11-27 09:58 - 斌 徐

- 状态 从 已解决 变更为 已关闭

- 指派给 从 涛 陆 变更为 云浩 汪

回归测试