

FORD LDM Localization - 功能 #2878

功能 # 2519 (已关闭): Ford_SYSR: System Requirement
功能 # 2548 (已关闭): Ford_SYSR : FS_REQ0028_V1 DRL Response to Low Beam outage

Ford_SWER_0028_0001 : DRL Response to Low Beam outage for dataset

2024-10-29 14:29 - 玉洁 金

状态:	已关闭	开始日期:	2024-10-29
优先级:	普通	计划完成日期:	2024-10-31
指派给:	培源 左	% 完成:	100%
类别:		预期时间:	0.00 小时
目标版本:	H003_SW0007169.A001.8	耗时:	0.00 小时
描述 “ DRL_LB_Outage_cfg ” will determine if DRL is affected by LB outage(0x00、0x01、0x02) Need to select the value of “ DRL_LB_Outage_cfg ” in the dataset; 0x00h: DRL will not be affected by LB outage. 0x01h: DRL will be affected by LB outage. When LB failure and LB is configured to turn off with failure, If DRL requested, DRL will dim to “ ParkPos_Intensity_cfg ” ; If POS requested, it should keep “ ParkPos_Intensity_cfg ” . 0x02h: DRL will be affected by LB outage. When LB failure and LB is configured to turn off with failure, If DRL requested, it can be activated with ‘ DRL_Intensity_cfg ’ ; If POS requested, it should be off.			

历史记录

- #1 - 2024-10-29 14:56 - 玉洁 金
- 主题 从 Ford_SWER : FS_REQ0028_V1 DRL Response to Low Beam outage 变更为 Ford_SWER_0028_V1 : DRL Response to Low Beam outage
- #2 - 2024-10-29 14:58 - 玉洁 金
- 主题 从 Ford_SWER_0028_V1 : DRL Response to Low Beam outage 变更为 Ford_SWER_0028_0001 : DRL Response to Low Beam outage
- #3 - 2024-10-29 15:11 - 培源 左
- 状态 从 新建 变更为 已解决
- % 完成 从 0 变更为 100
- #4 - 2024-10-31 09:15 - 玉洁 金
- 描述 已更新。
- #5 - 2024-10-31 16:02 - 斌 徐
- 指派给 从 培源 左 变更为 云浩 汪

编写测试用例

- #6 - 2024-10-31 18:23 - 玉洁 金
- 主题 从 Ford_SWER_0028_0001 : DRL Response to Low Beam outage 变更为 Ford_SWER_0028_0001 : DRL Response to Low Beam outage for dataset
- 描述 已更新。
- #7 - 2024-10-31 18:26 - 玉洁 金
- 描述 已更新。
- #8 - 2024-11-04 09:15 - 斌 徐
- 状态 从 已解决 变更为 已关闭
- 指派给 从 云浩 汪 变更为 培源 左

data set requirement

- #9 - 2024-11-05 08:54 - 涛 陆
- 描述 已更新。