

FORD LDM Localization - 功能 #2638

功能 # 2519 (已关闭): Ford_SYSR: System Requirement
功能 # 2531 (已关闭): Ford_SYSR : FS_REQ0011_V3 Turn Indicator Failsafe Mode

Ford_SWER_0011_0006 : Turn Indicator Failsafe Mode (Active Load Fault Reporting via LIN)

2024-10-25 16:06 - 培源 左

状态:	已关闭	开始日期:	2024-10-25
优先级:	普通	计划完成日期:	2024-12-13
指派给:	涛 陆	% 完成:	100%
类别:		预期时间:	0.00 小时
目标版本:	H005_SW0007169.A003.0	耗时:	0.00 小时
描述 软件进入到Failsafe Mode，且识别到有“ TI Power supply Channel ” (L/RF_Turn_Lamp_Ckt)使能，同时读取到Dataset中“ TI_POWER_Source_CFG ” 配置为0x01, “ Channel2/3/4_usage_cfg ” 配置为0x04时，若读取到Dataset生成的数据中“ TI_Failure_Report_cfg ” 配置为0x01时，TI需要满足Active Load Fault Reporting via LIN功能。 (The software enters Failsafe Mode and detects that TI Power supply Channel (L/RF_Turn_Lamp_Ckt) is enabled. When the value of TI_POWER_Source_CFG in the Dataset is 0x01 and the value of Channel2/3/4_usage_cfg is 0x04, If TI_Failure_Report_cfg is set to 0x01 in data generated by the Dataset, TI needs to meet the Active Load Fault Reporting via LIN function.)			

历史记录

#1 - 2024-10-28 16:41 - 培源 左

- 描述 已更新。
- 计划完成日期 被设置为 2024-10-31
- 状态 从 新建 变更为 已关闭
- 指派给 被设置为 涛 陆
- % 完成 从 0 变更为 100

#2 - 2024-10-29 13:38 - 斌 徐

- 状态 从 已关闭 变更为 已解决

#3 - 2024-10-30 10:11 - 培源 左

- 描述 已更新。

#4 - 2024-10-31 10:39 - 斌 徐

- 状态 从 已解决 变更为 进行中
- % 完成 从 100 变更为 50

#5 - 2024-11-01 09:52 - 培源 左

- 描述 已更新。

#6 - 2024-11-01 18:25 - 斌 徐

- 状态 从 进行中 变更为 已拒绝
- % 完成 从 50 变更为 100

在failsafe模式下，模块不能常供电，outage内部上拉，TURN故障不能一直报警

#7 - 2024-11-06 16:00 - 斌 徐

- 计划完成日期 从 2024-10-31 变更为 2024-11-13
- 状态 从 已拒绝 变更为 进行中

#8 - 2024-11-06 16:00 - 斌 徐

- 目标版本 从 H003_SW0007169.A001.8 变更为 H005_SW0007169.A003.0

#9 - 2024-11-06 16:01 - 斌 徐
- 计划完成日期 从 2024-11-13 变更为 2024-12-13

#10 - 2024-11-18 13:06 - 斌 徐
- 状态 从 进行中 变更为 已关闭