

FORD LDM Localization - 功能 #2685

功能 # 2519 (已关闭): Ford_SYSR: System Requirement
功能 # 2575 (已关闭): Ford_SYSR : FS_REQ0055_V3 LDM Failure Response Reporting

Ford_SWER_0055_0004 : LDM Failure Response Reporting-HB Failure Report cfg

2024-10-28 15:06 - 槐 杨

状态:	已关闭	开始日期:	2024-11-01				
优先级:	普通	计划完成日期:	2024-11-07				
指派给:	槐 杨	% 完成:	100%				
类别:		预期时间:	0.00 小时				
目标版本:	H003_SW0007169.A001.8	耗时:	0.00 小时				
描述 如果发生LED故障（LED串开载或短路（LED≥1个短路）），LDM应在主电源在保证性能范围内（9-18V），“ Ignition_status ”为“ Run/Start ”时，通过配置实现是否通过LIN总线报告故障。 (In case of a LED failure (LED string open load or short circuit (LEDs ≥1 short circuit)) the LDM shall be able to report the failure via LIN bus acc. to the following parameters when main power is within the range of guaranteed performance(9-18V) and ‘ Ignition_status ’ is Run/Start ‘ HB_Failure_Report_cfg ’ parameter definition: 0x00: LED string open load or short circuit (LEDs ≥1 short circuit) shall not be reported via LIN 0x01: LED string open load or short circuit (LEDs ≥1 short circuit) shall be reported via LIN) 相关的问题: <table><tr><td>复制到 功能 #2686: Ford_SWER_0055_0005 : LDM Failure Response Re...</td><td>已关闭</td><td>2024-11-01</td><td>2024-11-07</td></tr></table>				复制到 功能 #2686: Ford_SWER_0055_0005 : LDM Failure Response Re...	已关闭	2024-11-01	2024-11-07
复制到 功能 #2686: Ford_SWER_0055_0005 : LDM Failure Response Re...	已关闭	2024-11-01	2024-11-07				

历史记录

- #1 - 2024-10-28 15:07 - 槐 杨
- 主题 从 Ford_SWER_0055_0003 : LDM Failure Response Reporting-LB Failure Report cfg 变更为 Ford_SWER_0055_0004 : LDM Failure Response Reporting-HB Failure Report cfg

- 描述 已更新。
- #2 - 2024-10-28 15:08 - 槐 杨
- 复制到 功能 #2686: Ford_SWER_0055_0005 : LDM Failure Response Reporting-DRL Failure Report cfg 已添加
- #3 - 2024-10-31 18:53 - 斌 徐
- 计划完成日期 被设置为 2024-10-31

- 状态 从 新建 变更为 已解决

- 指派给 从 传鹏 胡 变更为 槐 杨

- % 完成 从 0 变更为 100
- 编写测试用例
- #4 - 2024-11-04 15:42 - 斌 徐
- 计划完成日期 从 2024-10-31 变更为 2024-11-07

- 开始日期 从 2024-10-28 变更为 2024-11-01
- #5 - 2024-11-21 09:10 - 斌 徐
- 状态 从 已解决 变更为 已关闭