

FORD LDM Localization - 功能 #2796

功能 # 2519 (已关闭): Ford_SYSR: System Requirement

功能 # 2592 (已关闭): Ford_SYSR : FS_REQ0071_V1 Description of Node Reporting

Ford_SWER_0071_0003 : Errors are reported once in LIN communicaiton

2024-10-29 10:46 - 斌 徐

状态:	已关闭	开始日期:	2024-10-29
优先级:	普通	计划完成日期:	2024-11-07
指派给:	涛 陆	% 完成:	100%
类别:		预期时间:	0.00 小时
目标版本:	H003_SW0007169.A001.8	耗时:	0.00 小时
描述			
All these faults are "one-shot." In other words, they are only reported once and then they are cleared and not reported again until they occur again.			
o DLPL_LIN_15_002 – Ford Standard J2602 Extension			

历史记录

- #1 - 2024-11-01 14:37 - 斌 徐
 - 计划完成日期 从 2024-10-31 变更为 2024-11-07
 - % 完成 从 0 变更为 70
- #2 - 2024-11-04 16:06 - 涛 陆
 - 状态 从 进行中 变更为 已解决
 - % 完成 从 70 变更为 100
- 软件完成
- #3 - 2024-11-21 10:15 - 斌 徐
 - 状态 从 已解决 变更为 已关闭