

FORD LDM Localization - 功能 #2861

功能 # 2519 (已关闭): Ford_SYSR: System Requirement

功能 # 2594 (已关闭): Ford_SYSR : FS_REQ0073_V1 Node Lighting Module Configuration Mechanics

Ford_SWER_0073_0012: LDM Data Configuration should respond “ Not configured ” immediately

2024-10-29 13:53 - 斌 徐

状态:	已关闭	开始日期:	2024-10-29
优先级:	普通	计划完成日期:	2024-11-07
指派给:	永琪 徐	% 完成:	100%
类别:		预期时间:	0.00 小时
目标版本:	H003_SW0007169.A001.8	耗时:	0.00 小时
描述			
DLPL_LIN_19_005		Once a node detects that the subnet as switched to Configuration Mode then it shall immediately start reporting "Not Configured" until the next requirement is met. The LIN Node must transmit the "Not Configured" status at least one time (even if the node does not support configuration information).	

历史记录

#1 - 2024-10-29 13:53 - 斌 徐

- 主题 从 Ford_SWER_0073_0011: LDM Data Configuration should respond “ Not configured ” immediately 变更为 Ford_SWER_0073_0012: LDM Data Configuration should respond “ Not configured ” immediately

#2 - 2024-11-01 16:34 - 斌 徐

- 计划完成日期 从 2024-10-31 变更为 2024-11-07
- 状态 从 进行中 变更为 已解决
- 指派给 从 涛陆 变更为 永琪 徐
- % 完成 从 0 变更为 100

BCM

#3 - 2024-11-22 09:37 - 斌 徐

- 状态 从 已解决 变更为 已关闭