

FORD LDM Localization - 功能 #2532

功能 # 2519 (已关闭): Ford_SYSR: System Requirement

Ford_SYSR : FS_REQ0012_V1 DRL Failsafe Mode

2024-10-24 17:48 - 玉洁 金

状态:	已关闭	开始日期:	2024-10-24
优先级:	普通	计划完成日期:	2024-10-31
指派给:	涛 陆	% 完成:	100%
类别:		预期时间:	0.00 小时
目标版本:	H003_SW0007169.A001.8	耗时:	0.00 小时

描述	
The input will be active in BCM failsafe mode, and only under DRL hardwire control condition, the DRL and all corresponding main functions of the DRL shall be operational only with “ DRL Power supply Channel ” (L/RF_DRL_Lamp_Ckt). Requirements for these specific functions will be described in following sections	
Function	Failsafe Requirement
DRL Light Output	Required
DRL Thermal Derating	Required
DRL Bin Sense	Required
Channel Open/Short Detection	Required
N-1 Failure Detection	Required (if enabled)
Active Load Fault Reporting via LIN	Required (if enabled)
Table 9: DRL failsafe strategy	

历史记录

#1 - 2024-10-24 17:50 - 玉洁 金

- 计划完成日期 被设置为 2024-10-31

#2 - 2024-10-25 09:31 - 涛 陆

需求取消，该硬线改为信号线

#3 - 2024-10-29 14:43 - 涛 陆

- 状态从 新建 变更为 已拒绝

- % 完成 从 0 变更为 100

#4 - 2024-10-31 14:03 - 斌 徐

- 状态从 已拒绝 变更为 已关闭