

FORD LDM Localization - 功能 #2660

功能 # 2519 (已关闭): Ford_SYSR: System Requirement
功能 # 2573 (已关闭): Ford_SYSR : FS_REQ0053_V2 General LED Failure Detection

Ford_SWER_0053_0003 : General LED Failure Detection_LIN feedback

2024-10-28 11:11 - 槐 杨

状态:	已关闭	开始日期:	2024-11-01
优先级:	普通	计划完成日期:	2024-11-07
指派给:	槐 杨	% 完成:	100%
类别:		预期时间:	0.00 小时
目标版本:	H003_SW0007169.A001.8	耗时:	0.00 小时
描述			
每次故障都需要通过LIN进行通信。在报告故障之前，需要至少在1秒内对故障进行10次验证。 该模块必须能够检测与LED相关的以下故障： • 单个或多个LED故障（每个通道） • 阳极到阴极短路 • 阳极到阴极断路 • BIN/NTC超出范围 (Each failure requires communication via LIN. The fault needs to be verified at least 10 times in 1 second before it can be reported. The module must be able to detect the following faults related to leds: • Single or multiple LED failures (per channel) • Short circuit from anode to cathode • Anode to cathode disconnect • BIN/NTC is out of range)			

历史记录

- #1 - 2024-10-28 11:16 - 槐 杨
- 主题 从 Ford_SWER_0001_0001 : General LED Failure Detection_LIN feedback 变更为 Ford_SWER_0001_0003 : General LED Failure Detection_LIN feedback
- #2 - 2024-10-28 14:29 - 槐 杨
- 主题 从 Ford_SWER_0001_0003 : General LED Failure Detection_LIN feedback 变更为 Ford_SWER_0053_0003 : General LED Failure Detection_LIN feedback
- 在1s内反馈故障
- #3 - 2024-10-31 18:37 - 斌 徐
- 计划完成日期 被设置为 2024-10-31
- 状态 从 新建 变更为 进行中
- 指派给 从 传鹏 胡 变更为 槐 杨
- % 完成 从 0 变更为 60
- #4 - 2024-10-31 18:41 - 斌 徐
- 描述 已更新。
- #5 - 2024-10-31 18:41 - 斌 徐
- % 完成 从 60 变更为 100
- #6 - 2024-11-04 15:24 - 斌 徐
- 计划完成日期 从 2024-10-31 变更为 2024-11-07
- 状态 从 进行中 变更为 已解决
- 开始日期 从 2024-10-28 变更为 2024-11-01
- #7 - 2024-11-19 10:50 - 斌 徐
- 状态 从 已解决 变更为 已关闭